

# TELEPÍTÉS

## Accessories

***IMAGES  
COMING  
SOON***

Please read all of the instructions and look at the pictures before attaching the holder.

1. Loosen the screws on the back of the holder to remove the bottom support.

2. Place the charging module as shown so that the holes fit.

Screw on the charging module.

3. Attach the cable:

Connect the cable in the port.

Place the enclosed lid over the cable and attach it with the enclosed screw.

4. The holder is in place.

**Az alábbiakkal kompatibilis**

Honeywell EDA10A